

### Property Inspection during tenancy

No.: 10/18/2012 000108 Date: 18/10/2012

#### **GENERAL**

Property Code	THE001
Property Address	2 The Street, Anywhere, Ireland
Tenants name(s)	Joe Blogs
Date Inspected	18/10/2012
Property alarmed	No
Property inspected by	Property manager

#### **ENTRANCE HALLWAY**

Flooring is in good condition, free from damage and is secure	Very good
The walls are clear of hooks, nails, holes and paint is in good condition	Very good
Ceiling is in good condition, free of stress cracks and water stains	Very good
Door(s), architraves and skirting are in good condition	Very good
Air vents are open/clear	No air vent
Any sign of mould or condensation	No
Door stop is secure and in proper location	No door stop
General condition of the room	Very good
Work required	
Entrance hallway photo 1	





Property Inspection during tenancy

Entrance hallway photo 2



No.: 10/18/2012 000108

Date: 18/10/2012

#### LIVING ROOM

Flooring is in good condition, free from damage and is secure	Very good
The walls are clear of hooks, nails, holes and	See comments
paint is in good condition	
Ceiling is in good condition, free of stress	Very good
cracks and water stains	
Door(s), architraves and skirting are in good	Very good
condition	
Air vents are open/clear	Yes
Any sign of mould or condensation	No
Window glass and handle are in good condition	Yes
General condition of the room	Very good
General Comments	
Some painting required where curtain pole has Work required	been moved

Paint where curtain pole has been moved



#### Property Inspection during tenancy

Livingroom photo 1



No.: 10/18/2012 000108

Date: 18/10/2012

#### Livingroom photo 2



#### Livingroom photo 3



#### **KITCHEN**

Flooring is in good condition, free from damage and is secure	Good
The walls are clear of hooks, nails, holes and paint is in good condition	Very good
Ceiling is in good condition, free of stress cracks and water stains	Very good



### Property Inspection during tenancy

Door(s), architraves and skirting are in good condition	Very good
Air vents are open/clear	Yes
Any sign of mould or condensation	No
Window glass and handle are in good condition	Yes
Counters are in good condition	Yes
Seal where counter meets wall and sink are	Yes
clean and in good condition	
There are no leaks from handle(s) or around	Yes
base of the tap/taps	
Fire extinguisher	No
Fire blanket	No
General condition of the room	Very good
Work required	
Penlace fire extinguisher and fire blanket	

Replace fire extinguisher and fire blanket Kitchen photo 1



No.: 10/18/2012 000108

Date: 18/10/2012

#### Kitchen photo 2





### Property Inspection during tenancy

Kitchen photo 3



No.: 10/18/2012 000108

Date: 18/10/2012


#### HALLWAY/STAIRS/LANDING

Flooring is in good condition, free from damage and is secure	Very good
The walls are clear of hooks, nails, holes and paint is in good condition	Very good
Ceiling is in good condition, free of stress cracks and water stains	Very good
Door(s), architraves and skirting are in good condition	Very good
Air vents are open/clear	Not applicable
Any sign of mould or condensation	No
General condition of the room	Very good



Property Inspection during tenancy

Hallway photo 1



No.: 10/18/2012 000108

Date: 18/10/2012

Hallway photo 2



#### **BATHROOM**

Flooring is in good condition, free from damage and secure	Very good
The walls are clear of hooks, nails, holes and paint is in good condition	Good
Ceiling is in good condition, free of stress cracks and water stains	Very good
Door(s), architraves and skirting are in good condition	Very good
Air vents are open/clear	Yes



### Property Inspection during tenancy

Window glass and handle are in good condition Extractor fan is functioning and is free of dust Counters are in good condition Seal where counter meets wall and sink are  handle broken Fan not working Not applicable Yes
Counters are in good condition  Seal where counter meets wall and sink are  Not applicable Yes
Seal where counter meets wall and sink are Yes
clean and in good condition
There are no leaks under the sink and the No leaks
ubend
There are no leaks from handle(s) or around Yes
base of the tap/taps
Shower screen/door/curtain and rail are in Good
good condition
Inspect bath/shower walls. Press tiles to check Very Good
for loose tiles and tiles are in good condition.
Seal is in good condition Yes
Toilet is free from leaks Yes
Toilet seat is in good condition and secure. Yes
Toilet is in good condition.
General condition of the room Very good
Work required

Repair window handle Repair extractor fan Bathroom photo 1



No.: 10/18/2012 000108

Date: 18/10/2012



Property Inspection during tenancy

Bathroom photo 2



No.: 10/18/2012 000108

Date: 18/10/2012

Bathroom photo 3





Property Inspection during tenancy

Bathroom photo 4



No.: 10/18/2012 000108

Date: 18/10/2012

#### BEDROOM 1

Flooring is in good condition, free from damage and is secure	Very good
The walls are clear of hooks, nails, holes and	Very good
paint is in good condition Ceiling is in good condition, free of stress	Very good
cracks and water stains	very good
Door(s), architraves and skirting are in good	Very good
condition	
Air vents are open/clear	Yes
Any sign of mould or condensation	No
Window glass and handle are in good condition	Yes
General condition of the room	Very good



#### Property Inspection during tenancy

Bedroom 1 photo 1



No.: 10/18/2012 000108

Date: 18/10/2012

#### Bedroom 1 photo 2



#### Bedroom 1 photo 3



#### BEDROOM 2

Flooring is in good condition, free from damage	Very good
and is secure	
The walls are clear of hooks, nails, holes and	Very good
paint is in good condition	
Ceiling is in good condition, free of stress	Cracks visible
cracks and water stains	



### Property Inspection during tenancy

Door(s), architraves and skirting are in good condition	Very good
Air vents are open/clear	Yes
Any sign of mould or condensation	No
Window glass and handle are in good condition	Yes
General condition of the room	Very good
General Comments	

Crack visible on ceiling. No work required. Bedroom 2 photo 1



No.: 10/18/2012 000108

Date: 18/10/2012

#### Bedroom 2 photo 2





### Property Inspection during tenancy

Date: 18/10/2012

No.: 10/18/2012 000108

Bedroom 2 photo 3



#### **BEDROOM 3**

Flooring is in good condition, free from damage and is secure	Very good
The walls are clear of hooks, nails, holes and	Very good
paint is in good condition	
Ceiling is in good condition, free of stress	Very good
cracks and water stains	
Door(s), architraves and skirting are in good	Very good
condition	
Air vents are open/clear	Yes
Any sign of mould or condensation	No
Window glass and handle are in good condition	Yes
General condition of the room	Very good



### Property Inspection during tenancy

Bedroom 3 photo 1



No.: 10/18/2012 000108

Date: 18/10/2012

Bedroom 3 photo 2





Property Inspection during tenancy

Bedroom 3 photo 3



No.: 10/18/2012 000108

Date: 18/10/2012

#### GENERAL INFORMATION

Overall general condition of the property

Property is in very good condition. The walls, ceilings and woodwork have been repainted. New carpet and curtains have been fitted throughout.

Yes

Service boiler

See comments for date of last service on boiler

Ensure that all windows and doors are locked Yes

before leaving the property

Reset alarm on leaving(only if alarm was on No alarm

when entering)

Engage mortice/double throw lock on leaving(only if lock was on when entering)

**General Comments** 

Boiler serviced 3 months ago

#### REAR EXTERIOR OF THE PROPERTY

Roof	Good
Gutters and drain pipes	Good
Facia	Fair
Chimney stack/pointing	Good
Doors	Good



### Property Inspection during tenancy

Windows	Good
Air vents are open/clear	Yes
Garden	See comments
General condition of the rear exterior	Very good
General comments	
Some paving slabs are uneven and may cause an accident Work required	
Level paving slabs Rear exterior photo 1	



No.: 10/18/2012 000108

Date: 18/10/2012



#### Property Inspection during tenancy

Rear exterior photo 2



No.: 10/18/2012 000108

Date: 18/10/2012

#### Rear exterior photo 3



#### FRONT EXTERIOR OF THE PROPERTY

Roof	Good
Gutters and drain pipes	Good
Facia	Good
Chimney stack/pointing	Good
Doors	Good
Windows	Good
Air vents are open/clear	Select one
Garden	See comments
General condition of the Front exterior	Good



Property Inspection during tenancy

General Comments

A tree has been cut from the garden and new grass seed planted.

Front exterior photo 1



No.: 10/18/2012 000108

Date: 18/10/2012

Front exterior photo 2



**DISCLAIMER** 



#### Property Inspection during tenancy

We did not carry out a detailed or structural survey of this property. We were not in a position to inspect the underfloor timbers or other parts of the structure which were covered, unexposed or inaccessible including electrical and plumbing services, and we are therefore unable to report that any such property is free from defect. Our inspection reports on the evidence visible on the exposed surfaces at the time of our inspection. We shall not be held liable for any faults or defects excluded from this report, whether visible, covered, unexposed or inaccessible.

No.: 10/18/2012 000108

Date: 18/10/2012